To: BOARD OF MANAGERS-PRESTONWOOD COUNTRY CLUB CONDOMINIUM ASSOC., INC.

From: Carrie Bailey
Subj: Manager's Report

I. Unfinished Business

## A. Operations

- Building Repair/Improvement Façade repairs new light fixtures & painting is complete on 15935 Coolwood. Address plaques are on order. Brick repairs completed at 5921 & 23 Copperwood. The next building renovation will be 15919 Stillwood.
- **2. Tamko Defective Rolled Roofing Replacement** –In response to the demand letter sent by RMWBH, Tamko has funded the replacement on Building E.
- 3. Parking Lot Striping & fire lane painting On hold until roofing is completed.
- **4. Underground Water Leaks –** Major leak in December repaired; no new leaks identified.
- **5.** New Trees Fannin Trees will replace the red buds that have died when the 3" caliper trees are harvested February or March. There will be no charge to the Association.
- **6. Common Ceiling Replacements** Two buildings pending.
- 7. Landscaping Bare Roots Landscape Solutions began service on 12/8/2021
- **8. Utility Building Controlled Access -** Bids are in process for a card entry system for the door from the pool to the Meeting Room and the door to the Laundry Room.
- 9. Generator Lease from Daikin for January 3, 2022, through February 28, 2022, as Potential Freeze Damage Protection Generator was delivered and connected on 1/3/2022. Pending weather forecasts for March, the generator will be removed on 2/28 reducing the cost to \$27,777.

## B. Administration

- 1. Owner Insurance Certificates on going
- 2. Occupancy Status Report 2021 Cap 50 –50 approved to lease- 4 are on waiting list.
- 3. Sales 2015/28 2016/30 2017/20 2018/17 2019/27 2020/21 2021/36 2022/1
- **4. Covid-19** On 8/11/2021 Judge Clay Jenkins issued new mask requirements & the Board approved policy: All are required to wear masks while inside Common & Limited Common Areas.
- 5. Reserve Study Draft completed. Corrections are being made and the final is due in February.

## II. New Business

- **A. New Signs** No exit, condo parking and right turn only at entrance.
- B. Card access for Pool Gates
- C. Cooling Towers Epoxy coating of lower portion of outside panels above the air intakes, install new lower overlay panels and louver retaining hardware. Prevents corrosion for 7-10 years. Daikin Applied \$10,900
- **D.** Chiller 2/Cooling Tower Bypass Valve Original scope of work for chiller replacement did not include needed for optimal performance during lower temperatures. Daikin Applied \$26,370.
- **E. Exterminator Change –** Certi-tech reducing insurance coverage. Bids from Protex and Terminix.
- **F.** Fannie Mae/Freddie Mac Condo Questionnaire Revisions RMWBH recommending a release from both the seller and the buyer in advance of providing information.
- III. Owner Hearing RMWBH's Leah Burton will preside.